



# Incident Information

Office of Public Affairs & Education

Date:	04/17/10	Adults Injured:	None				
Time Call Received:	1431 hours	Minors Injured:	None				
Incident Type:	Structure Fire	Civilian Fatalities:	None				
Address/Location:	2801 S. College Ave.	Civilians Rescued:	None				
Incident No:	10-4648	Firefighter Injuries:	None				
Occupancy Name:	Wok & Roll Teriyaki Restaurant	Firefighter Fatalities:	None				
Occupancy / # Units	Restaurant/One	Pet / Animal Fatalities/ Injuries:	None				
1 <sup>st</sup> In Company:	Engine 3	Assisting Agencies:	Fort Collins Police Services, Larimer County Dept. of Health				
Battalion:	One	Incident Control Time:	N/AV				
Dollar Loss:	N/AV	Incident Duration:	N/AV				
Dollars Saved:	\$500,000+	Total # Alarms:	Two				
Displaced/Evacuated:	N/AV	Total # Personnel	25				
Origin:	Cooking area	Incident Commander:	J. Pietrangelo				
Cause:	N/AV	Submitted by:	Patrick Love 1800 hours				
<b>Engines</b>	<b>Ladder Trucks</b>	<b>Brush Engines</b>	<b>Rescues</b>	<b>Ambulances</b>	<b>Water Tenders</b>	<b>Command Units</b>	<b>Investigators</b>
Five	Two	None	None	Two	None	One	One

Fort Collins, CO –Poudre Fire Authority responded this afternoon to a report of a kitchen fire at the above stated address. The first due engine found a one-story restaurant with smoke showing from the roof and north side of the building. Upon entry firefighters found light smoke throughout the restaurant with the most being in the kitchen. They found the fire on the cook top grill had been mostly extinguished by the dry chemical extinguishing system. However there was still some active fire on the grill and in the wall. The remaining fire was quickly extinguished.

Crews also performed tasks such as searches for occupants and ventilated smoke and heat.

The fire damage in the kitchen was relatively minor due to the quick response of the dry chemical hood and duct fire system. The entire restaurant however suffered smoke damage and will most likely be closed for at least the next twenty-four hours.

The origin and cause is currently under investigation.

This is the second fire within one week involving a restaurant cooking area.

###